



---

**Project:** *Underwater Inspection & Scour Evaluation*  
**Location:** *Salisbury, Connecticut*  
**Owner:** *Connecticut Department of Transportation*

---

**A.DiCesare Associates performed an underwater inspection, hydraulic study and hydraulic analysis and evaluation for US Route 7 over the Housatonic River in Salisbury, CT. Plagued by years of continual scour around the river piers, the project objective was to establish the parameters for remediation and preparation of Contract Documents for repair.**

---

*A.DiCesare Associates, P.C.*